Surficial geology and geomorphology of the Kumtor Gold Mine, Kyrgyzstan: human impacts on mountain glacier landsystems.

Journal:	*Journal of Maps*
Manuscript ID:	TJOM-2015-0060.R1
Manuscript Type:	Original Article
Date Submitted by the Author:	n/a
Complete List of Authors:	Evans, David,John,Alexander; University of Durham, Geography Ewertowski, Marek; Durham University, Geography Jamieson, Stewart; Durham University, Geography Orton, Chris; Durham University, Department of Geography
Keywords:	mountain glacier landsystem, human impacts, mining, Kyrgyzstan

1 Surficial geology and geomorphology of the Kumtor Gold Mine,

2 Kyrgyzstan: human impacts on mountain glacier landsystems.

3

4 David J. A. Evans, Marek Ewertowski, Stewart S.R. Jamieson and Chris Orton

5 Department of Geography, Durham University, South Road, Durham DH1 3LE, UK

6

7   **Abstract**

8   A 1:50,000 scale map of the surficial geology and geomorphology of the mountain glacier

9   landsystem and the human impacts of the Kumtor gold mine operations in the Akshiirak massif was

10   compiled from a 0.5 m resolution pan-sharpened image from Digital Globe's WorldView-2 platform

11   dating to September 5[th] 2014. The map depicts eleven surficial geology units, six of which are

12   classified according to natural genetic origins and five relating to recent human interference with

13   glaciological and land surface processes. When compared to historical imagery the map records a

14   number of important, not unrelated, cryospheric responses to mining activity, including: a) the

15   triggering of human-induced glacier speed-up events or surges due to dumping of mine spoil on

16   receding and thinning glacier snouts; b) the reactivation by internal creep of buried glacier ice due to

17   the expansion of spoil dumping onto down valley areas of ice-cored moraine; and c) accelerated ice

18   draw-down and significant incursions of ice into the mine pit walls due to the artificial removal of

19   substantial areas of glacier ablation zones.

20   **Key words:** mountain glacier landsystem; human impacts; mining; Kyrgyzstan

21   **Introduction**

22   Since 1997 the glacierized alpine terrain on the northwest corner of the Akshiirak massif of the Tien

23   Shan Mountains of Kyrgyzstan has been the site of the Kumtor gold mine (Kronenberg 2014), where

24   a super quarry has been operated at an altitude of 4,000 m asl. (Fig. 1). The deep excavations have

25   been carried out over an area of ca. 4.5 km^2 in some of the most severe environmental conditions

26   for mining anywhere in the world, where the Petrov, Lysii, Davidov, Sarytor and Bordoo glaciers flow

27   into deep mountain valleys from their high altitude cirque basins located at elevations above 4200 m

28   asl.. Unusually for such mining, the mine operators have had to excavate through glacier ice before

29   accessing the bedrock (Fig. 2), initiating some unique engineering problems (Fig. 3) and a full scale

30   experiment in debris loading-triggered glacier speed-up events (surges; Jamieson et al. in press).

31   Specifically, the mining process has necessitated the stockpiling of significant rock waste and

32   quarried glacier ice on adjacent, undisturbed glacier surfaces and stagnant snouts. Waste dumping

33   and land modification for mine infrastructure has affected an area of approximately 9.3 km^2.

34

35   The map presented here captures the state of the Kumtor mine and surrounding glacierized alpine

36   terrain in 2014, after seventeen years of quarrying and waste dumping of both glacier ice and

37   excavated rock material on permafrost that is characterized by significant areas of buried glacier

38   (ground) ice. Regularly captured satellite images have enabled us to identify the first examples of

39   human-triggered glacier speed up events or surges, which have been just some of the cryospheric

40   responses to mining disturbance since 1997 (Jamieson et al. in press). The influence of this

41   disturbance can be charted, and the pre-mining natural glacial landsystem signature determined,

42   from historical satellite imagery and aerial photography (Fig. 4). The natural glacial landsystem

43   comprises alpine style cirque and valley glaciers with polythermal snouts prone to occasional surging

44   (Aizen et al. 2006). Hence the glacial geomorphology is characterized by: a) extensive areas of valley

45   floor ice-cored moraine (including controlled moraine) derived from the melt out of englacial debris

46   bands and/or the concentration of rock avalanche debris in the ablation zone; b) fluted till surfaces,

47   that lie up valley from ice-cored moraine and attest to subglacial deforming layers and hence

48   temperate thermal conditions. The association of fluted till surfaces and ice-cored moraine arcs is

49   diagnostic of polythermal snouts in other glacial settings such as Svalbard and the central uplands of

50   Iceland. However, such a landform association would also not be unusual on the forelands of surging

51   glaciers. Historical trends in glacier activity for the area are dominated by snout recession (Kaulbars

52   1875; Davydov 1927; Kalesnik and Epstein 1935; Avsiuk 1953; Bondarev 1963; Sevast'yanov and

53   Funtikov 1981; Kuzmichenok 1990; Dyurgerov et al. 1995; Solomina et al. 2004; Aizen et al. 2006;

54   Jansky et al. 2009; Engel et al. 2012) but a very small number of glaciers advanced during the 20th

55   century, predominantly it would appear through surging (Dolgushin and Osipova 1982; Solomina et

56   al. 2004). In the area of the Kumtor mine, the Davidov Glacier terminus advanced 240 m between

57   1964 and 1980 and aerial images indicate that the snout had developed a steepening and crevassed

58   snout by 1977, indicating that a readvance or potential surge was likely underway at that time.

59   Imagery indicates that after 1977 and up until 2002 the glacier was in recession. The 2014 map

60   presented here contains evidence of glacier and bedrock mining in alpine glacierized terrain, waste

61   and ice dumping and cryospheric responses to such disturbances that include human triggered

62   glacier speed up events (surges) and stagnant ice reactivation and permafrost creep.

63   **Map production**

64   The surficial geology and geomorphology map of the Kumtor mine area of the Akshiirak massif was

65   compiled from a 0.5 m resolution pan-sharpened image from Digital Globe's WorldView-2 platform

66   dating to September 5th 2014. Contours at 100 m interval were derived from Advanced Spaceborne

67   Thermal Emission and Reflection Radiometer (Aster) Global Digital Elevation Model (GDEM) version

68   2, which is a product of METI and NASA (http://gdem.ersdac.jspacesystems.or.jp/). The GDEM data

69   therefore represents a landsurface that has since been modified by mine excavation and dumping.

70   Accordingly, contours were excluded over the mine excavation site and large areas of spoil dumping

71   because significant elevation changes had taken place in these areas since the ASTER GDEM

72   generation. The map is produced in UTM 44N projection (EPSG code: 32644) with WGS 1984 datum.

73   The map is at a scale of 1:50,000 if printed at A0 paper size.

74   The base data for the geomorphology and surficial geology was compiled using the 2014 imagery on

75   a coloured ink film overlay. Final map design and production was undertaken in Adobe Illustrator. A

76   raster image was used for the glacier surfaces by extracting them directly from the satellite image

77   and transposing a false blue colourised tint, allowing the display of features such as crevasses,

78   snowlines and supraglacial debris patterns.

79

80   **Surficial geology and geomorphology of the Kumtor mine area**

81   In addition to the cirque and valley glaciers and extensive bedrock outcrops, which occur mostly in

82   the steeper mountain terrain as alpine summits and slopes, the map is divided into eleven surficial

83   geology units, six of which are classified according to natural genetic, predominantly glacial, origins

84   and five relating to recent human interference with glaciological and land surface processes. The

85   area is characterized by continuous mountain permafrost up to 250 m thick (Redmond et al. 2011)

86   and hence surface materials will be perennially frozen below the active layer and, in areas beyond

87   the modern glacier extents, stagnant glacier ice with a debris cover that exceeds the active layer

88   thickness should be classified as ground ice.

89   *Ice-cored hummocky terrain*

90   Areas of ice-cored hummocky terrain are conspicuous by their kettled appearance and numerous

91   discontinuous, largely curved or sinuous ridges indicative of controlled moraine development on

92   debris-charged snouts (*sensu* Evans 2009). They occur as 0.25 to 1.5 km wide arcuate, latero-frontal

93   moraines, located at the historical maximum and more recent ice-marginal positions of the main

94   outlet glaciers. Hence the lateral components lie adjacent to the present glacier margins and the

95   frontal components up to 2 km down valley. More closely spaced and continuous ridges associated

96   with sparse kettle holes likely relate to the construction of push moraines in previously ice-cored

97   hummocks (i.e. incremental stagnation, *sensu* Eyles 1979; Bennett & Evans 2012). Lower relief

98   kettled topography within the areas classified as ice-cored hummocky terrain likely represents

99   moraine that has undergone advanced melt out. In 2014, ice-cored terrain was visible around the

100   western shore of Petrov Lake (the proglacial and supraglacial lake of the Petrov Glacier, Fig. 5a) and

101   the lower valleys of the Lysii and Bordoo (Fig. 5b) glaciers. Prior to spoil tipping, large areas of ice-

102   cored moraine also existed in the lower parts of the Davidov and Sarytor glacier valleys (Fig. 4a, b).

103   As the ice-cored terrain has survived more than one summer of melting and has been detached from

104   the active glacier snouts, it is now classified as ground ice.

Lake sediments and ephemeral lakes

106   Since the onset of mining at Kumtor, runoff has been directed to the "tailings management facility"

107   (Fig. 1b), a reservoir settling pond created by the construction of a dam in the Kumtor Valley. The

108   sediment infill in 2014 was partially exposed due to the lowering of the lake water level. The sands

109   and gravels deposited immediately above the normal water line have formed fan deltas where re-

110   directed glacial meltwater has either entered the lake via canals or spilled from the dam summit

111   canal; these deposits are classified as glacifluvial outwash even though they have been re-directed to

112   the reservoir.

Till and associated glacigenic materials

114   Tills are readily visible over small areas of recently deglaciated mountain valley floors, where they

115   appear fluted (Fig. 5b) and hence relate to the passage of temperate basal ice of the polythermal

116   glacier snouts when they extended to their historical, potentially Little Ice Age, maximum positions.

117   On older (pre-Little Ice Age) glaciated surfaces, tills locally thicken to degraded moraines and include

118   small areas of paraglacially modified material and outwash located in minor channels. As the older

119   tills have been modified by periglacial processes their surfaces display patterned ground features

120   and hence subglacial landforms cannot be recognized from aerial imagery.

Glacifluvial deposits

122   Glacifluvial deposits comprise coarse-grained gravels and sands predominantly organized in valley

123   floor outwash trains or linear sandar. On older glacial deposits, ribbons of glacifluvial material occur

124   on the floors of inter-moraine channels, particularly well-illustrated on the north side of the Kumtor

125   Valley. Pitted outwash occurs around the margins of Petrov Lake where glacifluvial deposits have

126   been prograded over stagnant glacier ice. Some small outwash fans did exist at the base of the

127   smaller cirque outlet valleys above the lower Lysii valley (Fig. 4a, b) but these have been

128   substantially reworked by mining activities (see heavily modified outwash).

Paraglacial deposits

130   Paraglacial deposits include those materials recently reworked by cold climate slope processes and

131   conditioned by recent deglaciation. They occur on the steeper slopes of the alpine terrain and

132   include reworked glacigenic material, scree slopes and debris flow fans.

133

Residuum and weathered glacigenic materials

Some lower angled slopes and wider mountain summits are draped by residuum or the products of in situ weathering, predominantly frost shattering, of bedrock. Blockfield also occurs on the mountain summits and is characterized by boulder-rich rubble, locally developed into patterned ground. Thin veneers of glacigenic materials are also included in this category as they have often been heavily reworked by periglacial processes.

Mining spoil dumped on glacier ice

The excavation of the mine has created large volumes of waste material and more latterly this contains a significant proportion of glacier ice, as the ablation zone of the Davidov Glacier is being gradually removed from the expanding south quarry face (Figs. 2 & 6). The gradual increase in supraglacially dumped spoil has been mapped by Jamieson et al. (in press) based upon repeat satellite imagery from 2002-2014 and can be seen to initiate reactivation of formerly stagnant ice/hummocky ice-cored terrain and speed-up (surge) activity in the lower Davidov snout and Lysii Cirque Glacier. This is manifest in the 2014 map as crevasses opening up beneath the supraglacial spoil and major compressional bulge fronts in some areas of the thickest spoil (Fig. 7) where the combination of increased overburden and relatively steep slopes have initiated internal creep.

Made ground

Large areas of the map are characterized by human modification of surface materials into hard standing for buildings, roads, tracks, canals and associated embankments (Figs. 2, 3 & 8). An extensive dam has also been constructed across the broad N-S trending valley in the immediate foothills to the west of the mountain range in order to produce a large settling lake. The most substantial area of made ground is the main mine, which is characterized by multiple terraced bedrock cliffs and access tracks, excavated to a depth of 500 m (Figs. 2 & 6). The map also captures the early stages of mine expansion towards the southwest and into the catchment of the Bordoo Glacier (Fig. 5b).

Heavily and moderately modified outwash

The glacifluvial outwash that formerly covered the outer foreland of the Petrov Glacier and the neighbouring floor of the Kumtor River Valley (Fig. 4a, b), where it has not been flooded by the settling lake, has been extensively modified by the removal of aggregate for the local construction of made ground. This is classified as heavily modified where original drainage patterns are difficult or impossible to discern and moderately modified where extraction has not eradicated such patterns.

166   *Older glacial deposits reactivated by permafrost creep*

167   Some spectacular deformation structures are apparent in three locations where it appears that the

168   permafrozen older glacial deposits have been subject to creep. This is marked by major

169   compressional bulge fronts, where the upslope or up-valley masses of mining spoil and glacier ice

170   have impinged upon the older glacial deposits, causing them to undergo compression and thrust

171   stacking (Fig. 7a). Because the formerly stagnant glacier ice has been reactivated by spoil dumping,

172   the construction of compressional forms is effectively a glacitectonic process and hence the

173   permafrost creep structures are anthropogenic thrust block or composite moraines, the first

174   examples of such features ever reported.

175   **Implications of mapping human-induced landscape change at Kumtor Mine**

176   The impact of mining activities on cryospheric systems, particularly glaciers, is not new (e.g. Eyles &

177   Rogerson 1977a, b; Melvold et al. 2003; Brenning 2008) but the ever increasing demand for rare

178   earths to satisfy the consumer demands of an expanding global population has led inevitably to the

179   expansion of mining into cold climate regions and even into extreme glacierized catchments. Even

180   the removal of glaciers in order to access underlying mineral lodes is no longer regarded as

181   economically prohibitive (e.g Brenning 2008; Citterio et al. 2009; Kronenberg 2013; Colgan 2014;

182   Colgan & Arenson 2013) and a series of reports on progress with the Kumtor Mine detail exactly how

183   such a monumental task can be undertaken (Redmond et al. 2011; Thalenhorst et al. 2012; Reid et

184   al. 2015). Given this expansion of high impact mining into glacierized catchments it is important that

185   glacier science charts and quantifies the response of cryospheric systems and the map presented

186   with this paper signifies the initiation of such monitoring.

187   The impacts charted here record a number of important, not unrelated, cryospheric responses to

188   mining activity. First, the dumping of mine spoil on receding and thinning glacier snouts has initiated

189   the first ever recorded human-induced glacier speed-up events or surges (Jamieson et al. in press).

190   In addition to this, between 1999 and 2006 the Davidov Glacier had been artificially narrowed by

191   initial spoil dumping, further accelerating its flow rate (Jamieson et al. in press). Second, the

192   expansion of spoil dumping onto down valley areas of ice-cored moraine and buried glacier ice,

193   survival of which in a continuous permafrost zone constitutes ground ice, has triggered the

194   reactivation (internal creep) of the glacier ice due to increased overburden. Third, the removal of

195   substantial areas of the ablation zones of glaciers will inevitably result in continued, and likely

196   accelerated, ice drawdown from the accumulation zone, resulting in significant incursions of ice into

197 the pit walls and the need for costly mitigation, in the form of either ice-excavation or of temporary

198 barrier construction, to allow continued mine operation (Reid et al. 2015).

199 It is also interesting to speculate on what the future holds, especially as repeat imagery will facilitate

200 continued monitoring. Future quarrying will continue to drawdown substantial volumes of glacier ice

201 from the Davidov Glacier catchment and if this ice is not removed artificially (i.e. once the pit

202 becomes disused), the glacier will occupy an artificial bedrock overdeepening (Cook & Swift 2012).

203 Early stages of this will be characterized by ice calving into a deep proglacial lake, the lake water

204 being dammed by the gradually ablating, spoil-covered snout of the lower valley. This would likely

205 constitute a glacial lake outburst flood (GLOF) hazard (cf. Janský et al. 2009, 2010), especially as the

206 majority of the pit lies below the equilibrium line altitude and hence would constitute a

207 foreshortened ablation zone/reconstituted glacier (Benn & Lehmkuhl 2000) fed by ice fall collapse

208 and avalanching.

209

210

211 **Acknowledgements**

219

220

221 **References**

222 Aizen, V.B., Kuzmichenok, V.A., Surazakov, A.B., & Aizen, E.M. (2006). Glacier changes in the central

223 and northern Tien Shan during the last 140 years based on surface and remote sensing data.

224 *Annals of Glaciology*, 43, 202-213.

225 Avsiuk, G.A. (1953). Lednik Petrova (Petrov glacier). *Raboty Tyan'-Shanskoy Fiziko-Geograficheskoy*

226 *Stantsii* 2a. Izdatelsvto Akademii Nauk SSSR, Moscow, 103–131

227 Benn, D.I., & Lehmkuhl, F. (2000). Mass balance and equilibrium line altitudes of glacier in high

228 mountain environments. *Quaternary International,* 65/66, 15-29.

229 Bennett, G. L., & Evans, D. J. A. (2012). Glacier retreat and landform production on an overdeepened

230 glacier foreland: The debris-charged glacial landsystem at Kvíárjökull, Iceland. *Earth Surface*

231 *Processes and Landforms*, 37, 1584–1602.

232 Bondarev, L.G. (1963). *Ocherki po oledeneniyu massiva Ak-Shirak (Studies on the glaciation of the Ak-*

233 *Schyirak Range)*. Izdatelstvo Akademii Nauk Kirgizskoi SSR, Frunze.

234 Brenning, A. (2008). The Impact of Mining on Rock Glaciers and Glaciers: examples from central

235 Chile. In B.S. Orlove, E. Wiegandt & B. Luckman B. (Eds.), *Darkening Peaks: Glacier Retreat,*

236 *Science and Society* (pp.196-205). University of California Press: Berkeley.

237 Citterio, M., Mottram, R., Larsen, S.H. & Ahlstrøm, A. (2010). Glaciological investigations at the

238 Malmbjerg mining prospect, central East Greenland. *Geological Survey of Denmark and*

239 *Greenland Bulletin,* 17, 73–76.

240 Colgan, W. (2014). Considering the ice excavation required to establish and maintain an open ice pit.

241 *Journal of Cold Regions Engineering, 28*, doi:10.1061/(ASCE)CR.1943-5495.0000067

242 Colgan, W., & Arenson, L. (2013). Open-pit glacier ice excavation: brief review. *Journal of Cold*

243 *Regions Engineering, 27*, doi:10.1061/(ASCE)CR.1943-5495.0000057

244 Cook, S.J. , & Swift, D.A. (2012). Subglacial basins: their origin and importance in glacial systems and

245 landscapes. *Earth Science Reviews*, 115, 332-372.

246 Davydov, L.K. (1927). Lednik Petrova (Petrov glacier). *Trudy Gidromet. Otdel. Sred. Meteorol. Inst.,*

247 1(1), 67–100.

248 Dolgushin, L.D., & Osipova, G.B. (1982). *Pul'siruyushchie ledniki (Surging glaciers).* Gidrometeoizdat,

249 Leningrad.

250 Dyurgerov, M.B., Liu, C., & Xie, Z. (1995). *Oledenenie Tyan'-Shanya (Tien Shan glaciers).* VINITI,

251 Moscow.

252 Engel, Z., Sobr, M., & Yerokhin, S.A. (2012). Changes of Petrov glacier and its proglacial lake in the

253   Akshiirak massif, central Tien Shan, since 1977. *Journal of Glaciology*, 58, 388-398.

254   Evans, D.J.A. (2009). Controlled moraines: origins, characteristics and palaeoglaciological

255   implications. *Quaternary Science Reviews*, 28, 183–208.

256   Eyles, N. (1979). Facies of supraglacial sedimentation on Icelandic and Alpine temperate glaciers.

257   *Canadian Journal of Earth Science*, 16, 1341–1361.

258   Eyles, N., & Rogerson, R.J. (1977a). How to save your mine from a glacier. *Canadian Mining Journal*,

259   98, 32.

260   Eyles, N, & Rogerson, R.J. (1977b). Artificially induced thermokarst in active glacier ice: an example

261   from northwest British Columbia, Canada. *Journal of Glaciology,* 18, 437–444.

262   Jamieson, S.S.R., Ewertowski, M., & Evans, D.J.A. (in press). Rapid advance of two mountain glaciers

263   due to mine-related debris loading. *Journal of Geophysical Research – Earth Surface*.

264   Janský, B., Engel, Z., Sobr, M., Benes, V., Spacek, K., & Yerokhin, S. (2009). The evolution of Petrov

265   lake and moraine dam rupture risk (TienShan, Kyrgyzstan). *Natural Hazards,* 50, 83–96.

266   Janský B., Šobr, M., & Engel, Z. (2010). Outburst flood hazard: case studies from the Tien-Shan

267   Mountains, Kyrgyzstan. *Limnologica – Ecology and Management of Inland Waters,* 40, 358–

268   364.

269   Kalesnik, S.V., & Epstein, S.V. (1935). Lednikovij uzel Ak-Shyirak (Akshiirk glacier knot). *Trudi Lednik.

270   Exped.*, 2, 321–372

271   Kaulbars, A.V. (1875). Materiali po geographii Tien Shanya sobrannie vo vremya puteshestviya 1869

272   (Materials on Tien Shan geography, collected within 1869 expedition). *Proceedings of the

273   Russian Geographical Society*, 5, 253–539

274   Kronenberg, J. (2013). Linking ecological economics and political ecology to study mining, glaciers

275   and global warming. *Environmental Policy and Governance,* 23, 75–90.

276   Kronenberg, J. (2014). Viable alternatives for large-scale unsustainable projects in developing

277   countries: the case of the Kumtor gold mine in Kyrgyzstan. *Sustainable Development,* 22,

278   253-264.

279   Kuzmichenok, V.A. (1990). *Izmenenie lednikov khrebta Akshiirak c 1943 po 1977 godi.* (Scale 1 :

280   50,000) Main Department of Geodesy and Cartography of the USSR, Moscow.

281   Melvold, K., Schuler, T., & Lappegard, G. (2003). Ground-water intrusions in a mine beneath

282   Höganesbreen, Svalbard: assessing the possibility of evacuating water subglacially. *Annals of

283   Glaciology,* 37, 269–274.

284   Redmond, D., Thalenhorst, H., & Seto, J. (2011). *Technical Report on the Kumtor Gold Project,

285   Kyrgyz Republic, for Centerra Gold Inc.*. Toronto, Canada.

286   Reid, G.D., Wong, J., Raponi, T.R., D'Souza, K., Landry, P., Seto, J., & Chance, A. (2015). *Technical

287   *Report on the Kumtor Mine, Kyrgyz Republic, for Centerra Gold Inc..* Toronto, Canada.

288   Sevast'yanov, D.V., & Funtikov, A.B. (1981). Novy dannye ob evollucii vysokogornogo ozera u konca

289   lednika Petrova (New data on the evolution of the mountainous lake in front of the Petrov

290   glacier). *Izv. VGO,* 113(5), 430–435.

291   Solomina, O., Barry, R.G., & Bodnya, M. (2004). The retreat of Tien Shan glaciers (Kyrgyzstan) since

292   the Little Ice Age. *Geografiska Annaler,* 86(2), 205–215.

293   Thalenhorst, H., Redmond, D., Raponi, T.R., & Vdovin, V. (2012), *Technical Report on the Kumtor*

294   *Gold Project, Kyrgyz Republic, for Centerra Gold Inc..* Toronto, Canada.

295

296   **Figure captions**

297   Figure 1: Annotated satellite images and location maps of the Kumtor mine and the adjacent glaciers

298   and glaciated terrain in 2014: a) Landsat 8 platform image taken on 2014 May 14th (Data

299   available from the U.S. Geological Survey) showing the Akshiirak glacierized massif within

300   the Tien Shan mountains. The coverage of vertical aerial images in following figures is

301   demarcated; b) local glaciers and landscape surrounding the mine viewed in a 1.8 m

302   resolution image from Digital Globe's WorldView-2 platform (from Jamieson et al. in press).

303   The coverage and viewing direction (white arrow) of oblique aerial images in following

304   figures is demarcated.

305   Figure 2: View southwards across the mine in June 2012, showing the alpine terrain and the

306   appearance of glacier ice in the upper terraces on the pit wall where the Davidov Glacier is

307   being excavated (image from Thalenhorst et al 2012).

308   Figure 3: Mine infrastructure being bulldozed by permafrost creep below the Davidov Glacier mine

309   dump in April 2013 (Bruce Pannier's *Qishloq Ovozi* blog).

310   Figure 4: Pre- and post-mining imagery of the Akshiirak glaciers and surrounding terrain: a) Corona

311   image KH-4A (mission 1014-2) image dating to 1964 and annotated to show main glacial

312   landforms (Data available from the U.S. Geological Survey); b) KH-9 image (mission 1216-5)

313   image dating to 1980 and illustrating the relative stability of the glacier snouts, with the

314   exception of the Petrov calving margin, when compared to the 1964 imagery (Data available

315   from the U.S. Geological Survey). Note the Lysii Cirque Glacier prior to its covering with

316   mining spoil; c) oblique 2.4 m resolution Quickbird image of the Lysii cirque glacier front

317   (300-350 m wide) in 2002 during the initial stages of its speed-up/surge in response to

318   supraglacial mine waste dumping. Note that it has caused deformation of the Lysii Glacier

319   snout; d) oblique 2.4 m resolution Quickbird image of the Davidov Glacier snout in 2002

320   during the early stages of supraglacial mine waste dumping. Note the occurrence of ice-

321   cored hummocky moraine in the lower valley comprising outer, brown coloured and inner,

322   grey coloured zones, the latter containing more densely spaced linear ridges (controlled

323   moraine, *sensu* Evans 2009).

324   Figure 5: Examples of areas of ice-cored hummocky terrain extracted from Digital Globe's

325   WorldView-2 platform imagery taken on September 5[th] 2014: a) the historical moraines

326   damming the Petrov Glacier proglacial lake, showing an inner zone of large kettle holes and

327   discontinuous ridges (controlled moraine) and an outer zone of ice-cored push ridges; b) the

328   foreland of the Bordoo Glacier, showing ice-cored hummocky terrain forming a latero-

329   frontal arc around a valley floor covered in fluted till.

330   Figure 6: Aerial views of the main mine and its impact on the Davidov Glacier: a) view in 2003 from

331   Digital Globe's QuickBird platform imagery, when dumped mine rock waste was beginning to

332   impinge on the glacier surface; b) view extracted from Digital Globe's WorldView-2 platform

333   imagery taken on September 5[th] 2014, showing the result of excavation of the majority of

334   the Davidov Glacier ablation zone to leave a crevassed icefall from which ice is being

335   quarried.

336   Figure 7: Impacts of mining spoil dumping on the glacier snouts viewed from Digital Globe's

337   WorldView-2 platform imagery taken on September 5[th] 2014: a) the lower Davidov Glacier

338   valley, showing mining spoil with compressional bulge fronts (dark grey) and compressional

339   thrust ridge complexes created in permafrost (light grey and brown) by the advance of the

340   ice-cored mining spoil. Note the remains of buildings on the thrust ridges which were

341   gradually bulldozed (see Fig. 3) by the advancing wave of compressed material; b) the

342   rapidly advancing, spoil covered Lysii Cirque Glacier and its surface features of

343   compressional bulge fronts and crevasses (compare with Fig. 4b, c).

344   Figure 8: Example of made ground and mine infrastructure next to the Davidov Glacier prior to

345   extensive supraglacial spoil dumping and ice excavation (SRK Consulting).

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60



253x306mm (300 x 300 DPI)

181x219mm (300 x 300 DPI)

254x190mm (96 x 96 DPI)

224x110mm (96 x 96 DPI)

181x219mm (300 x 300 DPI)

181x219mm (300 x 300 DPI)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

338x190mm (96 x 96 DPI)

338x190mm (96 x 96 DPI)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

33x36mm (600 x 600 DPI)

24x17mm (600 x 600 DPI)

30x26mm (600 x 600 DPI)

30x26mm (600 x 600 DPI)

33x25mm (600 x 600 DPI)

33x35mm (600 x 600 DPI)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

546x201mm (72 x 72 DPI)

SURFICIAL GEOLOGY AND GEOMORPHOLOGY OF THE KUMTOR GOLD MINE, KYRGYZSTAN: HUMAN IMPACTS ON MOUNTAIN GLACIER LANDSYSTEMS

D.J.A. Evans, M. Ewertowski, S.S.R. Jamieson & C. Orton   Department of Geography, Durham University

NATURAL SURFICIAL UNITS

- Lake sediments and ephemeral lakes (reservoir / settling pond infill)
- Ice-cored hummocky terrain (including areas likely to have undergone advanced melt-out)
- Glacifluvial deposits
- Till and associated glacigenic materials (locally thickening to degraded moraines and including small areas of paraglacially modified material)
- Residuum and weathered glacigenic materials
- Paraglacial deposits (including periglacial slope materials and small areas of residuum and bedrock outcrops)

- Bedrock
- Glacier ice

ANTHROPOGENIC SURFICIAL UNITS

- Heavily modified outwash
- Moderately modified outwash
- Older glacial deposits reactivated by permafrost creep (thrust block moraines)
- Mining spoil dumped on glacier ice
- Made ground (see details at right)
- Crevasses developed in glacier ice overlain by mining spoil
- Flutings
- Relict channels on outwash and erosional meltwater channels
- Lakes and kettle holes
- Rivers
- Major terrace (fluvial in outwash; quarry levels and constructional benches in made ground)
- Major compressional bulge fronts and thrust structures (in till and associated glacigenic materials and mining spoil)
- Moraine ridges and controlled moraine in ice-cored terrain
- Track
- Contours

MADE GROUND DETAILS

- Quarried terraces / benches
- Canal
- Track (also on glacier ice)
- Track / road
- Disturbed surface or embankment
- Building
- Hard standing

N

0   kilometres   2

Scale 1:50,000

Compiled from 0.5m pan-sharpened image from Digital Globe's Worldview-2 platform, September 5th 2014

Contours derived from Aster GDEM Version 2

Contour interval 100m

UTM 44N projection

WGS 1984 datum

To accompany paper: Evans D.J.A., Ewertowski M., Jamieson S.S.R. & Orton C. (2015) *Surficial geology and geomorphology of the Kumtor Gold Mine, Kyrgyzstan: human impacts on mountain glacier landsystems. Journal of Maps.*

© Journal of Maps, 2015